
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: <u>5/26/2009</u>
Test to be performed: Ground Condition:   Smoke Dyed Water X Dry ✓ Damp Wet		Supervisor: <u>JAW</u>
Manhole_ID: S07MM_027MH	Test ID: <u>D1032-015022</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Water Level	
0			Manhole	S07MM_027MH
0			Dye Test Not Visible	